


Summary	Turbo Seal Insulated bollard Spacing			
Products Affected	Turbo Seal Insulated			
Key Word Tags	Bollard ,Minimum Width, TSI, Insulated Door			
Tools/Equipment (If Required)				
Parts/Materials (If Required)				
Related Media				
Author	Jeff Malinowski, P. E.	Issue Date	7-19-13	Status Active


Please Read The Entire Bulletin Before Proceeding

Proper bollard spacing is important to ensure the break-away feature on Rytec industrial doors functions properly. Bollard spacing is also important to ensure appropriate side column maintenance access. To facilitate both, Rytec suggests the following minimum spacing used for bollards on their Turbo Seal Insulated door line:

- No bollard surface should be closer than 18" from the face of the mounting wall
- No bollard surface should extend in to the rough opening more than 2" beyond the rough opening jamb.



Side view



Front View